ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura

Street ID	Street Name	Significant Landmark
W0237, W0118, W0069, W0241, W0130, W0261, W0128, W	NA	Durga Layout Main road and Cross Roads

Segment No.	Total Length (m)
9/C-W0237/S102801	698.41

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	126.82	77.562441	13.078203	77.563575	13.077924	W0241	DEAD END
2	320.35	77.562646	13.079159	77.563830	13.077464	W0118	DEAD END
3	183.42	77.562348	13.079256	77.562287	13.077853	W0118	W0241
4	67.82	77.562056	13.079394	77.562646	13.079190	W0233	W0241

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Durga Layout Main road and Cross Roads in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	1500000	2013

Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Improvements to Durga Layout Main road and Cross Roads in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	009-13-000026

Work Order No.	Work Order Date	Period of Extention
EE/BTP/BBMP/E-TND/WO/159/2013-14	09/10/2013	60 DAY

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
30/05/2014	29/05/2015	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
H S NATARAJ		0.00

Phone No.	E-Mail ID
9448474325	

Field Inspection Details

Number of Trees	Any Other Information	Name
14		SURESH

Date of Inspection	Remarks
29/12/2016	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0237, W0118, W0069, W0241,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	29/12/2016	28/01/2017	COMPLETED
SE	VASU K M	29/12/2016	28/01/2017	COMPLETED
EE	SRINIVAS REDDY	29/12/2016	28/01/2017	COMPLETED
AEE	PRAKESH	29/12/2016	28/01/2017	COMPLETED
AE	SURESH	29/12/2016	28/01/2017	COMPLETED
AE	SURESH	29/12/2016	28/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0237, W0118, W0069, W0241,